

ANNUAL BACKFLOW PREVENTION ASSEMBLY TEST & MAINTENANCE REPORT

(Required by Texas Commission on Environmental Quality, State of Texas)

**Brinker WSC
4534 I-30 East
Sulphur Springs, TX 75482**

Date: March 18, 2026

Name:
RE: Account

It is time for the **ANNUAL TESTING** of your Backflow Prevention Assembly, as required by the Texas Commission on Environmental Quality (TCEQ). ***Title 30 of the Texas Administrative Code 290.44(h)(4)-(6)*** We strongly encourage having your system winterized and tested before reactivating your system in the Spring.

With sprinkler/irrigation systems, you are served by an on-site sewage facility, so the irrigation system is designated a health hazard and shall be connected to the water source through a **Reduced Pressure Principle Backflow Prevention Assembly (RPBA)** to prevent cross contamination between your sewer and drinking water.

If you currently have a DOUBLE CHECK installed, it must be replaced with an RPBA. *Title 30 of the Texas Administrative Code 344.51(d)(2); 344.50(b)(2)(a)(b)*

You may use any tester that you choose, if they are a Licensed Backflow Prevention Assembly (BPA) Tester. The original test and maintenance report must be provided to us **within 10 days** of the test as specified in ***Title 30 of the Texas Administrative Code 290.44(h)(4)(c); 344.50(e)***. It will be your responsibility to pay the tester directly.

Here is a list of a few licensed testers in our area:

Custom Ventures	Terry Irwin	903-495-2139
Summerhouse Lawn & Garden	Reece Booher	903-885-4083
Millers Backflow & CSI	Michael Miller	903-730-1029
Chris' Landscape & Irrigation	Chris Keller	903-885-4885
Derek Anderson	Derek Anderson	214-808-9216
M/S Landscapes	Steven Bindeman	903-439-7340

*****We must have this report in our office no later than May 29, 2026.**

If you have any questions, please call our office at 908-885-8888.

Thank you,

**Scott Courson – General Manager
Brinker WSC**